

LONG TERM OBSERVATIONS OF A 3-SPAN HIGHWAY CORRUGATED STEEL BOX BRIDGE ON GNIEZNO BYPASS

Arkadiusz MADAJ^{*}, Maciej WĘGRZYŃSKI^{**}, Leszek JANUSZ^{***}

^{*}) PhD, Prof., Poznań University of Technology, Poland

^{**}) MScCEng, ViaCon Polska, Rydzyna, Poland

^{***}) PhD C Eng, ViaCon Polska, Rydzyna, Poland

Abstract

The paper describes 5 years of behavior of a corrugated steel box 3 span bridge with a 14.1m span. The bridge is located on Gniezno by-pass in Poland. After few months of operation road surface over the bridge showed signs of ruts. An expertise was performed to evaluate causes of rut formation and provide suggestions for repair of the bridge. Deformations of road surface, structure and foundations were measured.

Key words: corrugated steel box, measurements, deformations, long term, repair

1. INTRODUCTION

The first triple deep corrugated corrugated steel box bridge in Europe located on the bypass of Gniezno in Poland was built in 2004/2005. The aim of it was to cross the land with high thickness of organic soil and peat. There is also a local road and drainage ditch under the viaduct. These types of structures have been used in Europe since 2000 (Madaj et Janusz 2008).

The structure was designed to carry a class A live load acc. to PN-85/S-10030.

Each of the three boxes have following parameters:

- rise - 3.7 m,
- span - 14.075 m,
- bottom length - 23.56 m,
- skew angle - 90°,
- corrugation - 380 × 140 mm,
- plate thickness/rib thickness - 7.00 mm,
- bevels - 1:1.5,
- minimum cover : 1.0 m.

The corrosion protection was the 85 μm of zinc coating and additionally the inside of the structure was painted with 200 μm of epoxy. The structure was

reinforced by means of additional ribs situated on the whole perimeter in the distance of 1143 mm.

Steel structures were designed to be backfilled with the use of 0-32 mm sand-gravel mix compacted to Standard Proctor density of minimum 97%.

As a preventive measure gainst rain water a layer of 1,5 mm HDPE geomembrane and 500g/m² non-woven has been placed over the structures.



Figure 1 Deep corrugated steel box grade separation under construction



Figure 2 Ready bridge directly after completion

The by-pass is a busy road carrying heavy trucks that are allowed on national roads in Poland. The bridge was built on very poor, soft, compressive soil (i.e. peats, silts, gytja) reaching down to 10,4 m. The reinforced concrete foundations were placed on steel piles driven into the subsoil.

2. PERFORMANCE OF THE BRIDGE IN SERVICE

One year after the construction the road administration noticed signs of deflection of road surface located over the spans of the bridge. Moreover, settlement of soil at boths ends of the bridge abutment as well as underneath pile cappings were

recorded. In order to limit further settlement of embankment near bridge abutments, concrete restraining beams placed on Larsensteel piles were built in 2006 (Figure 4 a). It turned out, settlement persisted despite this installation. Figure 4b shows space under capping of the piles after 6 years of performance



Figure 4 a) View of concrete beams placed on Larsen steel piles (walls) at the bottom of the embankment; b) view of space under pile capping

The deformations of the surface were reflected in the deformations of the steel bridge parapets which were installed alongside both ends of the bridge (Figure 5).



Figure 5 View of deformed parapets



Fig. 6 Outlet of drain with fine particles that are washed - out from the backfill



Fig. 7. Visible settlement of paved bevel end of the bridge




Fig. 9 Deflection measured in the crown of the corrugated steel structure in km 1+892,41




Fig. 10. Deflection of road surface measured in km 1+892,41

Changes between initial measurement and final measurement for asphalt road surface and crown of the span in left side (L), middle (S) and right side (P) locations were recorded. The below table shows maximum differences at km 1+892,41 (Table 1)

Table 1. Maximum changes of levels (deflections) of road surface and steel structure during measurement period

km	[m]	[m]	[m]
1+892,41	L	S	P
road	-0,052	-0,024	-0,064
structure	-0,034	-0,059	-0,037

3. DISCUSSION OF RESULTS AND CONCLUSIONS

From the results obtained from measurements one can observe that there has been some deflection of corrugated structures in the crown. Maximum level measured over 5 years was 59 mm, which is 42% of the allowed deflection (140 mm) (CHBDC). Deflection has basically stabilized from 2007 to 2010. Deflections of the road surface were mostly progressing from 2005 to 2007 and since then the incremental change was minor, finally reaching the maximum level of 49 mm in 2008. There was no direct correlation between deflection of the road surface and deflection of the crown of the structures e.g. in km 1+892,41 in location (S) the final change in road surface was -0,024 m and the crown deflected -0,059 m. Opposite observations relate to other measurement points. Basically, foundations have been very stable. This conclusion was presented also in an expertise by (Madaj, 2008). Other independent expertise by (Gryczmański et al., 2008) concludes that the main result of the road surface deflection is settlement of the of road embankment at the abutments of the bridge. The difference between deflection of road surface in measurements points was caused by behavior of asphalt under live load (point S is located at road centerline which is affected less by the wheels of moving vehicles). In 2008 the top layer of road surface over the bridge has been replaced as the first repair measure. Observations of the bridge behavior from that moment on don't show alarming results. The bridge performs well. Authors are convinced that one of the reasons is that the consolidation of the soil has occurred and no major settlements of the embankment has occurred recently. Generally it is of importance when building such types of bridges to be especially careful with backfill and other surrounding soil that would contribute to soil-structure interaction in order to avoid problems during service.

REFERENCES

1. Madaj A. Janusz L. (2009): *Obiekty inżynierskie z blach falistych, Projektowanie i Wykonawstwo*. Warszawa, WKŁ.
2. CSA, Canadian Highway Bridge Design Code, Canadian Standards Association - International
3. Madaj A (2008): *Ocena przyczyn deformacji nawierzchni na konstrukcji typu multi-plate w ciągu drogi krajowej nr 15 w Gnieźnie*. Politechnika Poznańska
4. Gryczmański M, Łupieżowiec M. (2008): *Analiza przyczyn deformacji nawierzchni na konstrukcji mostowej SuperCor Box*. Politechnika Śląska

Streszczenie

Praca opisuje 5-letnie zachowanie trójprzęsłowego mostu skrzynkowego o rozpiętości 14,1 m. Most znajduje się na obwodnicy Gniezna w Polsce. Po kilku miesiącach użytkowania na powierzchni drogi nad mostem pojawiły się koleiny. Przeprowadzono badanie w celu oceny przyczyn powstawania kolein i przygotowania propozycji naprawy mostu. Dokonano pomiarów odkształceń powierzchni drogi, konstrukcji mostu oraz fundamentów.

Słowa kluczowe: skrzynki z blachy falistej, pomiary, odkształcenia, długi okres, naprawy

